


CPS utility software installation required before operations.


DJMD5 update

* DJMD5 Update mode


Turn on the power while pressing PF1 and PF2
Indicator blinks in red



* Firmware update tool



Please open "spi" file



After connecting the radio,
please select COM port

Click "Write" to write


Never turn off the radio while updating. Also please use a fully charged battery

After updating, the radio restarts automatically

* Confirmation after updating

Follow the steps below to check the Firmware version

- 1 Press the menu key (Green key) to enter the main menu
- 2 Select "settings" using up / down keys
- 3 Select "3 Device Info"
- 4 Confirm "Firmware Ver" using down key



Replace the most updated utility software with old one. Older utility won't work correctly.
This update can be applied to any version of MD5, but older hardware won't support some of features this version offers.